EPL No:	<u>11436</u>	
Date:	20/07/2022	

Date	Time	Method	Туре	Location	Description	Response/action taken to resolve the complaint
16/07/2022	8:45:00 am	E-mail	Odour		Wind was reported to be a Light W or NW wind.	An assessment of meteorological data and operational activity has been completed in order to investigate the potential source or cause of odour was undertaken. In consulation with the NSW EPA, an in-depth and detailed analysis approach to investigating reports of odour is being undertaken.
15/07/2022	11:15:00 am	Community Feedback Line	Odour		during the two previous evenings. They described the odour to by ever so slightly different from usual, more sulfuric possibly.	An assessment of meteorological data and operational activity has been completed in order to investigate the potential source or cause of odour was undertaken. In consulation with the NSW EPA, an in-depth and detailed analysis approach to investigating reports of odour is being undertaken.

## Licensee:

Veolia Environmental Services (Australia) Pty Ltd Cnr Unwin & Shirley Streets, Rosehill NSW 2142

## Premises:

Woodlawn Landfill Collector Road, Tarago NSW 2580