



EPL No: 11436
 Date: 16/05/2024

Date	Time	Method	Type	Location	Proximity to Site	Description	Wind Rose Chart/Map	Av. Wind Speed (m/s)	Av. Wind Direction	Bar. Pressure (hPa)	Temp 10m, Av (°C)	Activity on site consistent with normal operation?	Action taken or proposed to be taken to deal with the incident and/or prevent a recurrence	Photograph of active landfill cell showing intermediate cover (closest to complaint date) [1]	Current level of leachate in each pond at most the most recent survey	Daily H2S Non Zero Value Average (PPB)	Mechanical evaporator run times on onset of odour complaint	Correlation with wind direction (Y/N)	Conclusion
12/05/2024	15:00	Website Feedback Form	Odour	Carneys Road, Currawang	Approximately 10 km North North West of the site	Notifier advised they detected an odour from between 3pm to 6pm. The odour waste rated as a 4 on the odour intensity scale and was described as Rubbish/Garbage. The weather conditions were reported to be overcast, mild and temperature of 11 degrees.		3.597	South Eastern Wind Complainant was downwind of the premises.	930.726	11.72	Y	Veolia has engaged The Odour Unit to undertake a gas characterisation assessment to determine the presence of other odour gases. Veolia will continue to implement the recommendations within the 2023 Odour Audit.		Date: 30/04/2024 ED3N-1: 791.69 ED3N-2: 791.64 ED3N-3: 791.64 ED3N-4: 793.85 ED3S-5: 793.35	Point 9 - 0 Point 71 - 0 Point 72 - 0	5:15am - 6:15pm	Y	An assessment of meteorological data and operational activity has been completed in order to investigate the potential source or cause of odour was undertaken with no significant impacts evident at the time of the complaint. Veolia acknowledges that the premises is potentially the source of the odour detected by the complainant based on the wind direction. It is noted that no H2S was detected at the monitoring station on site and the H2S monitors did not detect H2S within Tarago on 12/05/2024.

Licensee:
 Veolia Environmental Services (Australia) Pty Ltd
 Cor Unwin & Shirley Streets, Rosehill NSW 2142

Premises:
 Woodlawn Landfill
 Collector Road, Tarago NSW 2580

[1] Photo